

Safety Communication

رسالة سلامة

Device malfunction causing the applier to jam, and clip loading failures

Device/ Product Description:	A Li-Gator Single Use Laparoscopic Clip Applier	
Affected products:	Model:	360-010-001
	Codes:	8250 I8251 I8252 I8820 I8821 I8822 I8823 I8824 I8825 I9571-A I9572-A I9573-A I9716-A I9717-A I9718-A I9719-A J0113-A J0114-A J0115-A J0225-A J0227-A J0228-A J0229-A J0230-A J0231-A J0240- A J0243-A J0287-A
Manufacturer:	Genicon, Inc.	
Problem:	Device malfunction causing the applier to jam, and clip loading failures.	
Recommendation /Actions:	<p>Contact Genicon to coordinate the return of the product associated with this action at no additional cost.</p> <p>For more information, please click here.</p> <p>If you think you had a problem with your device or a device your patient uses, please report the problem to SFDA through: NCMDR Vigilance system (19999) unified call center</p>	
Authorized Representative Details	AR name:	Medical Regulations Gate
	Assigned Contact Person:	Abdulaziz Alqahtani
	Mobile/Phone:	+(966) 506121295
	Email:	Ameen@mr-gate.com