Safety Communication رسالة سلامة

Risk of not pre-programmed insulin pump

Device/ Product Description:	MiniMed 600 and 700 series insulin pump
Affected product:	MiniMed™ 640G: MMT-1711, MMT-1712, MMT-1751, MMT-1752 MiniMed™ 670G: MMT-1780, MMT-1781, MMT-1782, MMT-1760, MMT-1761, MMT-1762, MMT-1741, MMT-1742 MiniMed™ 720G: MMT-1809, MMT-1810, MMT-1859, MMT-1860 MiniMed™ 740G: MMT-1811, MMT-1812, MMT-1861, MMT-1862 MiniMed™ 770G: MMT-1881, MMT-1882, MMT-1892, MMT-1891 MiniMed™ 780G: MMT-1885, MMT-1886, MMT-1895, MMT-1896
Manufacturer:	Medtronic SA
Problem:	The new/replacement pump was NOT pre-programmed with the patient's basal rates or other verified settings (i.e., bolus wizard settings, sensor settings, etc.), which must be set up and saved on their pump prior to use.

<table>
<tr><td>Recommendation /Actions:</td><td colspan="2">- Inform impacted users of the MiniMed™ 600 and 700 series insulin pump using the enclosed letter in the attached FSN.

For more information, please click here

If you think you had a problem with your device or a device your patient uses, please report the problem to SFDA through:
NCMDR
Vigilance system
(19999) unified call center</td></tr>
<tr><td rowspan="4">Authorized Representative Details</td><td>AR name:</td><td>Medtronic Saudi Arabia</td></tr>
<tr><td>Assigned Contact Person:</td><td>Faisal Mansour Matbuli</td></tr>
<tr><td>Mobile/Phone:</td><td>0535355500</td></tr>
<tr><td>Email:</td><td>ksa.ra@medtronic.com</td></tr>
</table>